## EXHIBIT D

## **BMH Mechanical**

Brandon Huberty **Business Number** 781-552-0542

225D Fallon Rd #393

Stoneham MA

02180

Bmhmechanical@gmail.com

INVOICE INVO407

DATE Dec 5, 2023

DUE On Receipt

BALANCE DUE USD \$808.71

**BILL TO** 

## Jack Keverian

Jack 25 Bancroft Watertown MA Jkeveria@gmail.com

DESCRIPTION	RATE	QTY	AMOUNT
HVAC Inspection	\$808.71	1	\$808.71

Returned to Glancy's warehouse for a final inspection. The units were moved and allowed me to gain full access to all areas of the units that were inaccessible before. I found that the units were cleaned thoroughly and most of the spot rust had been removed/treated with galvanized paint. Now that the units were completely accessible, I was able to access both blowers and electrical sections on all units. I have some concerns with the integrity of the fan motors. It appears that more than 1/2 of the motors bearings are audibly loud and stiff. This is most likely the cause of condensation forming in the motors sealed bearings and rusting. Also, there are some transformers that have an excessive amount of rust. I took some videos of them compared to one of the new units. My suggestion is replacement of both fan motors in the 11 units and at least 1/2 of the transformers on the units that were stored outside. My concern is that all the motors are compromised on the 11 outdoor units. Attached is some pictures of transformers and I will forward videos of motors turning.

Scan this code to pay online

BALANCE DUE

USD \$808.71







